

**APPENDIX E:**

**PHOTOGRAPHS**

**PHOTOGRAPH INDEX  
PHOTOGRAPHS**

*This **APPENDIX** provides an **Indexed Listing** of the attached photographs; the **Location** pictured; the **Homogeneous Area and/or Functional Space** represented; as well as the respective **Bulk Sample Number** associated with the photograph. Copies of actual photographs are also included.*

### PHOTOGRAPH INDEX

*This **SUB-APPENDIX** provides an **Indexed Listing** of the attached photographs; the **Location** pictured; the **Homogeneous Area and/or Functional Space** represented; as well as the respective **Bulk Sample Number** associated with the photograph.*

PHOTOGRAPH INDEX

<b>Photograph Number</b>	<b>Location</b>	<b>Homogeneous Area</b>	<b>Functional Space</b>	<b>Sample Number</b>
1.	517 Gold Federal Building (NM0024ZZ) Albuquerque, New Mexico			N/A
2.	517 Gold Federal Building (NM0024ZZ) Albuquerque, New Mexico			N/A
3.	Room 5408	9"x9" Floor Tile	Office	034B
4.	Room 1028	9"x9" Floor Tile	Office	030B
5.	Room 1011	12x12 Floor Tile and Mastic	RR Foyer	041B
6.	Room 1011 1/2	12x12 Floor Tile and Mastic	Janitor Closet	044B
7.	Room 1307G	12x12 Floor Tile and Mastic	Restroom	047B
8.	Boiler Room	Boiler #4 Insulation	Mechanical	117B
9.	Boiler Room	Boiler Breeching	Mechanical	118B
10.	Boiler Room	Hot Water Generator Insulation	Mechanical	138B
11.	Boiler Room	Boiler Breeching	Mechanical	118B
12.	Boiler Room	Air Handler Duct	Mechanical	N/A
13.	Boiler Room	Steam System Fittings	Mechanical	133B
14.	Boiler Room	Drinking Water Fittings	Mechanical	125B
15.	Boiler Room	Steam System Fittings	Mechanical	133B

**PHOTOGRAPHS**

*This SUB-APPENDIX provides a copy of ACTUAL PHOTOGRAPHS taken during the Asbestos Building Audit Survey.*






*Photo 1: 517 Gold Federal Building (NM0024ZZ) Albuquerque, New Mexico*




*Photo 2: 517 Gold Federal Building (NM0024ZZ) Albuquerque, New Mexico*





*Photo 3: 9" X 9" floor tile exists throughout most of the building and is usually covered by carpet.*




*Photo 4: 9" X 9" floor tile exists throughout most of the building and is usually covered by carpet.*






*Photo 5: Mastic beneath beige floor tile in Restroom vestibules contains asbestos.*




*Photo 6: Asbestos-containing floor tile and mastic was identified in each janitor closet.*






*Photo 7: Mastic beneath 1'x1' floor tile in Rooms 1307G & 1307H contains asbestos.*




*Photo 8: Insulation on Boiler #4 in Room S24 contains asbestos.*






*Photo 9: Insulation on both round and square boiler flues (breaching) contains asbestos.*




*Photo 10: Expansion Tank Insulation in Boiler Room contains asbestos.*






**Photo 11:** *Insulation on both round and square boiler flues (breaching) contains asbestos.*




**Photo 12:** *Exterior of Air Handler Duct is not insulated.*






*Photo 13: Steam Lines Fitting Insulation in Room S24 contain asbestos.*




*Photo 14: Drinking Water Supply Lines Fitting Insulation in Room S24 contains asbestos.*





*Photo 15: Boiler and Chiller Cold Water Lines Fitting Insulation in Room S24 contains asbestos.*



*Photo 16: Typical steam system fittings located in boiler room contain asbestos.*